



1. WinAIR Flange
2. Small bolts
3. Screws
4. Allen key

## Installation

- Install WinAIR pressure gauge onto the Flange by using the small bolts
- Use the Screws to panel mount the assembly

